

Water Test Update

The faucet, associated piping, and backflow preventer have been replaced. The system was retested; the test results came back negative with the levels below the threshold of 15ppb (0.015mg/L).